/2.37	Improved the strong spurious emissions of approximately 1 MHz bandwidth	
/2.36	Fixed some unknown issue.	
/2.35	Fixed some unknown issue.	
/2.34	Fixed the problem for example set the frequency 446.00625Mhz,but only display 446.0065Mhz.	
/2.33	 Fixed an issue where the monitor volume during transmission could not be changed. Fixed an issue where the transmit interface was displayed earlier. Fixed an issue where the offset was incorrect during MR to VFO. 	