


RETEVIS MA1 Software and Firmware Changelog



Main Board Firmware Version V2.43

1. Fixed a bug where RX ONLY menu settings were not saved.
2. Added a 1-second delay to the boot character display.
3. Modified the microphone's custom button menu.


Main Board Firmware Version V2.42


1. Reduced the volume threshold for levels 1-4.


Main Board Firmware Version V2.41

1. Added RX Only to the menu, with On/Off options. If RX OFF is selected, the machine should not display an error message but instead show RX ONLY.
2. Added a scan switch to the microphone's custom button.
4. Used the same button to toggle between VFO and MR custom functions instead of two separate buttons.
5. Added microphone gain to the menu and simultaneously added it to the microphone's programmable button.
6. Added a weather forecast function. Enabled by F+CTRL.

Date: 20250326

 E_TM_MA1_LCD_V1.8sV1.bin

 E_TM_MA1_V2.23.bin

 MA1_V3.0_Setup.exe

Changelog: 1. Add channel name display record.

2. Added mic gain setting item.

3. Fixed the squelch noise and volume issue.